

COUNCIL WORKSHOP ITEM

ITEM: File #07-01
DATE: June 14, 2001
PREPARED BY: Robert Schiller, Traffic Manager
PURPOSE: Approve the Parking & Traffic Commission's recommendation to restrict parking on Concord Drive as specified below.

DISCUSSION:

Staff has reviewed the parking conditions and determined that vehicles parked on the north side of Concord in close proximity to the intersections of Stonewall and Bunker Hill cause significant site distance problems for safe access. Therefore, staff recommends placement of "No Parking Here to Corner" restrictions at a point of 50' east and west of Bunker Hill and 50' east and west of Stonewall. These restrictions should provide adequate site distance for vehicles to safely enter Concord Drive.

ATTACHMENT:

Further discussion regarding this file can be found on pages 2 through 6 in the May 15, 2001 Parking & Traffic Commission minutes

RECOMMENDATION:

At the May 15, 2001 Parking & Traffic Commission meeting the Commission moved to recommend to the Village Council to restrict parking on the north side of Concord Drive 50 feet east and west of Bunker Hill and on the north side of Concord Drive 50 feet east and west of Stonewall and to provide adequate sight distance so vehicles can safely enter Concord Drive.

