



General Information

Street Number: 4521
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0905315005

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Good
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Bungalow
Number of Stories: 1
Current Wall Material 1: Wood Shingles
Current Wall Material 2:
Original Wall Material 1: Wood Shingles
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: steps newer



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Stoop

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Vinyl

Window Detail: Ribbon

Window Storms: No

Significant Features:



General Information

Street Number: 4525
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0905315006

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Good
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Bungalow
Number of Stories: 1
Current Wall Material 1: Vinyl Siding
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: re-sided, steps newer



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Stoop

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Ribbon

Window Storms: Yes

Significant Features:



General Information

Street Number: 4529

Former Street Number:

Street: MAIN STREET

PIN Number(s): 0905315007

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Bungalow

Number of Stories: 1

Current Wall Material 1: Wood Shingles

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: re-sided



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch:

Dormers: Shed

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes




Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: July 10, 2013



General Information

Street Number: 4533

Former Street Number:

Street: MAIN STREET

PIN Number(s): 0905315008

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Poor

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Bungalow

Number of Stories: 1

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Stoop

Dormers: Shed

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features:



General Information

Street Number: 4536

Former Street Number:

Street: MAIN STREET

PIN Number(s): 0905314008

Construction Date/Other Year: 1910s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Gable Front Cottage/House

Number of Stories: 1 ½

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations: re-sided, replacement windows



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: No

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Detached garage. September 1968. Frank L. Werneske. Owner. GC.

Horizontal lines for notes




Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: July 10, 2013



General Information

Street Number: 4537
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0905315009

Construction Date/Other Year: 1900s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Good
Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Gable Front Cottage/House
Number of Stories: 1 ½
Current Wall Material 1: Asbestos Siding
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled
Roof Material: Asphalt Shingle

Alterations: porch removed, re-sided, shutters added, replacement windows



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stucco

Door Detailing: Surrounds
Porch: Stoop

Dormers: Pedimented

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: No

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: July 10, 2013



General Information

Street Number: 4600
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0905322013

Construction Date/Other Year: 1950s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Poor
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Minimal Traditional

Ornamentation: classical entry surround

Building Form:
Number of Stories: 1 ½
Current Wall Material 1: Aluminum Siding
Current Wall Material 2:
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled
Roof Material: Asphalt Shingle

Alterations: re-sided, replacement windows



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Surrounds
Porch: Stoop
Dormers: Pedimented
Window Type: Double-Hung
Window Configuration: Multi-Paned
Window Material: Vinyl
Window Detail:
Window Storms: No

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Detached Garage. April 1951. Detached garage extension. November 1962.

Bay windows. front. July 1995.

Horizontal lines for note-taking.



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: July 10, 2013



General Information

Street Number: 4604
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0905322014

Construction Date/Other Year: 1950s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Poor
Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Ornamentation: gable siding

Building Form: Ranch

Number of Stories: 1

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: re-sided, replacement windows



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: No

Significant Features:



General Information

Street Number: 4608
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0905322015

Construction Date/Other Year: 1950s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Good
Secondary Structure Integrity: Poor
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Ranch
Number of Stories: 1
Current Wall Material 1: Vinyl Siding
Current Wall Material 2:
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled
Roof Material: Asphalt Shingle

Alterations: re-sided



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features:



General Information

Street Number: 4612

Former Street Number:

Street: MAIN STREET

PIN Number(s): 0905322016

Construction Date/Other Year: 1950s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Ranch

Number of Stories: 1

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations: re-sided, replacement windows



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail: Paired

Window Storms: No

Significant Features:



General Information

Street Number: 4613
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0905323003

Construction Date/Other Year: 1949

Architect: Wight & Company
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Poor
Secondary Structure: Garage
Secondary Structure Condition: Good
Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Minimal Traditional

Ornamentation:

Building Form:

Number of Stories: 1 ½

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations: porch removed or entry area altered, re-sided, replacement windows



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: No

Significant Features:



Research Information

Original Building Owner: Reeve

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information: Wight & Company

Architect 2 Information:

Contractor Information: Hultman

Developer Information:

Research/Archival Information:

Permit: Yes

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:




Photo 2

Notes

Built 1949. Reeve Family. Owner. Wright & Co. (Downers Grove).
Architect
Hultman (Hinsdale). GC. Addition & Dormers. September 1958.
Chester Reardon. Owner. \$1,200.00. Garage. June 1963. E.J.
Bratney. Owner. Robert E. Cooper. GC. \$1,300.00.

Horizontal lines for additional notes




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: July 10, 2013



General Information

Street Number: 4616
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0905322017

Construction Date/Other Year: 1950s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Good
Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Ranch
Number of Stories: 1
Current Wall Material 1: Aluminum Siding
Current Wall Material 2:
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled
Roof Material: Asphalt Shingle

Alterations: replacement windows



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail: Ribbon

Window Storms: No

Significant Features:



General Information

Street Number: 4617
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0905323004

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Good
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Foursquare
Number of Stories: 2
Current Wall Material 1: Vinyl Siding
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: re-sided, shutters added



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4620
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0905322018

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent

Secondary Structure:
Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: classical porch

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: stucco may have been added historically



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Sidelights

Porch: Entrance

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: porch



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Detached Garage. February 1956. Albert Lalonde. Owner. \$900.00.

Horizontal lines for notes




Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: July 10, 2013



General Information

Street Number: 4621
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0905323005

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Good
Secondary Structure Integrity: Good
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Bungalow
Number of Stories: 1 ½
Current Wall Material 1: Wood Shingles
Current Wall Material 2: Vinyl Siding
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled
Roof Material: Asphalt Shingle

Alterations: porch infilled, dormers added



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Stoop

Dormers: Shed

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail:

Window Storms:

Significant Features:



General Information

Street Number: 4624
 Former Street Number:
 Street: MAIN STREET
 PIN Number(s): 0905322019
 Construction Date/Other Year: 1928
 Architect:
 Current Function/Category: Single Family Residential Building
 Historic Function: Single Family Residential Building
 Listing in Existing Survey:

Evaluation

Condition: Good
 Integrity: Good
 Secondary Structure: Garage
 Secondary Structure Condition: Excellent
 Secondary Structure Integrity:
 Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:
 Ornamentation:
 Building Form: Foursquare
 Number of Stories: 2
 Current Wall Material 1: Vinyl Siding
 Current Wall Material 2:
 Original Wall Material 1: Wood clapboard
 Original Wall Material 2:
 Wall Detailing/Ornamentation:
 Storefront Material:
 Roof Type: Hipped
 Roof Material: Asphalt Shingle
 Alterations: re-sided, replacement windows



Photo 1

Significant: No
 National Register Criterion:
 Contributing to a National Register District: C
 Potentially Contributing to a National Register District: Noteworthy Buildings
 Less Than 50 Years Old: No
 Reason for Significance:

Roof Ornamentation:
 Foundation Material/Form: Concrete/Concrete Block
 Door Detailing:
 Porch: Entrance
 Dormers: Pedimented
 Window Type: Double-Hung
 Window Configuration: 1 over 1
 Window Material: Vinyl
 Window Detail:
 Window Storms: No
 Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Detached garage. February 1998. Bruce Strang. Owner. Danley Lumber. GC.

Horizontal lines for notes




Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: July 10, 2013



General Information

Street Number: 4625
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0905323006

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Poor
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Bungalow
Number of Stories: 1
Current Wall Material 1: Wood Shingles
Current Wall Material 2:
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled
Roof Material: Asphalt Shingle

Alterations: may be re-sided, porch enclosed, steps newer



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Partial

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes




Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: July 10, 2013



General Information

Street Number: 4628

Former Street Number:

Street: MAIN STREET

PIN Number(s): 0905322020

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Foursquare

Number of Stories: 2

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Entrance

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4629

Former Street Number:

Street: MAIN STREET

PIN Number(s): 0905323007

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Bungalow

Number of Stories: 1 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: newer steps



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4633
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0905323008

Construction Date/Other Year: 1950s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Minimal Traditional

Ornamentation: bay window

Building Form:
Number of Stories: 1 ½
Current Wall Material 1: Vinyl Siding
Current Wall Material 2:
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled
Roof Material: Asphalt Shingle

Alterations: re-sided, replacement windows



Photo 1

Significant: No

National Register Criterion:
Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:
Porch: Entrance

Dormers:
Window Type: Double-Hung
Window Configuration: Multi-Paned
Window Material: Vinyl
Window Detail: Paired
Window Storms: No

Significant Features:



General Information

Street Number: 4636

Former Street Number:

Street: MAIN STREET

PIN Number(s): 0905322022

Construction Date/Other Year: 1950s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Good

Secondary Structure: Attached Garage

Secondary Structure Condition:

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Minimal Traditional

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations: re-sided, shutters added, portico removed



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4637
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0905323009 -10

Construction Date/Other Year: 1970s

Architect: Joseph Pluhar
Current Function/Category: Single Family Residential Building
Historic Function:
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity:
Secondary Structure: Attached Garage
Secondary Structure Condition:
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Neo Revival

Ornamentation:
Building Form:
Number of Stories: 2
Current Wall Material 1: Vinyl Siding
Current Wall Material 2:
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:
Roof Type: Front Gabled
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No
National Register Criterion:
Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Surrounds
Porch: Stoop

Dormers:
Window Type: Double-Hung
Window Configuration: Multi-Paned
Window Material: Vinyl
Window Detail: Paired
Window Storms: No

Significant Features:



General Information

Street Number: 4640
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0905322023

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Poor
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Bungalow
Number of Stories: 1 ½
Current Wall Material 1: Vinyl Siding
Current Wall Material 2:
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled
Roof Material: Asphalt Shingle

Alterations: front addition, re-sided, replacement windows



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Stoop

Dormers: Shed

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Vinyl

Window Detail:

Window Storms:

Significant Features:



General Information

Street Number: 4644

Former Street Number:

Street: MAIN STREET

PIN Number(s): 0905322024

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation: brackets

Building Form: Bungalow

Number of Stories: 1 ½

Current Wall Material 1: Wood Shingles

Current Wall Material 2:

Original Wall Material 1: Wood Shingles

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: porch enclosed, replacement windows



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Stoop

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Vinyl

Window Detail: Ribbon

Window Storms:

Significant Features:



General Information

Street Number: 4704

Former Street Number:

Street: MAIN STREET

PIN Number(s): 0908102012 -13

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Poor

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation: shingles, arched porch openings

Building Form: Gable-Ell

Number of Stories: 1 ½

Current Wall Material 1: Stucco

Current Wall Material 2: Wood Shingles

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: porch stairs newer, 2nd garage is not historic



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Porch: Partial

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: unique roof form



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Double lot. original garage is on corner lot. Detached Garage. Mach 1982. Richard A. Newbery. Owner. Hankinson Lumber (Lisle). GC.

Horizontal lines for note-taking.



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: April 30, 2013



General Information

Street Number: 4705
Former Street Number: 169
Street: MAIN STREET
PIN Number(s): 0908103002

Construction Date/Other Year: 1910s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Bungalow

Number of Stories: 1

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: replacement sided and windows



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Full Front

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: No

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Attached car port. October 1951. Elmer Chessman. Owner & GC.

Horizontal lines for notes




Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: April 30, 2013



General Information

Street Number: 4707
Former Street Number: 167
Street: MAIN STREET
PIN Number(s): 0908103003

Construction Date/Other Year: 1910s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Poor

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Bungalow

Number of Stories: 1

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: significantly altered, only original massing remains



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights

Porch:

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: No

Significant Features:



General Information

Street Number: 4708
Former Street Number: 166
Street: MAIN STREET
PIN Number(s): 0908102014

Construction Date/Other Year: 1910s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Poor

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Bungalow

Number of Stories: 1

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: small rear addition



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: original enclosed porch



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Detached Garage. October 1952. Mrs. Mildred Butela. Owner. Henry
Ottersen (Western Springs), GC.

Horizontal lines for notes




Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: April 30, 2013



General Information

Street Number: 4711
Former Street Number: 163
Street: MAIN STREET
PIN Number(s): 0908103004

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Multi Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Aluminum Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: replacement siding, newer period porch



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Stucco

Door Detailing:

Porch: Partial

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: bay windows and turret



General Information

Street Number: 4712

Former Street Number:

Street: MAIN STREET

PIN Number(s): 0908102015

Construction Date/Other Year: 1910s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Poor

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Foursquare

Number of Stories: 2

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: replacement siding, moved from original site



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4713
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908103005

Construction Date/Other Year: 1955

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure: Attached Garage
Secondary Structure Condition:
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Ranch
Number of Stories: 1
Current Wall Material 1: Wood clapboard
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: replacement windows, shutters added



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Partial

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4714
Former Street Number: 158
Street: MAIN STREET
PIN Number(s): 0908102016

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Multi Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation: shingles, classical portico

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2: Wood Shingles

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: stucco added, corner addition from c. 1930



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: irregular massing, prominent brick chimney



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit: No

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Detached Garage. March 1996. Gloria Verbeke. Owner. Better Built Lumber.

Horizontal lines for note-taking.



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: April 30, 2013



General Information

Street Number: 4716
Former Street Number: 156
Street: MAIN STREET
PIN Number(s): 0908102017

Construction Date/Other Year: 1900s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Poor

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Gable Front Cottage/House

Number of Stories: 2

Current Wall Material 1: Wood Shingles

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: porch removed, re-sided, replacement windows



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms:

Significant Features:



General Information

Street Number: 4717
 Former Street Number: 4719
 Street: MAIN STREET
 PIN Number(s): 0908103006
 Construction Date/Other Year: 1926
 Architect:
 Current Function/Category: Single Family Residential Building
 Historic Function: Single Family Residential Building
 Listing in Existing Survey:

Evaluation

Condition: Good
 Integrity: Good
 Secondary Structure: Garage
 Secondary Structure Condition: Excellent
 Secondary Structure Integrity: Excellent
 Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:
 Ornamentation:
 Building Form: Foursquare
 Number of Stories: 2
 Current Wall Material 1: Stucco
 Current Wall Material 2:
 Original Wall Material 1:
 Original Wall Material 2:
 Wall Detailing/Ornamentation:
 Storefront Material:
 Roof Type: Hipped
 Roof Material: Asphalt Shingle
 Alterations: replacement windows, porch enclosed, aluminum eaves



Photo 1

Significant: No
 National Register Criterion:
 Contributing to a National Register District: C
 Potentially Contributing to a National Register District: Noteworthy Buildings
 Less Than 50 Years Old: No
 Reason for Significance:

Roof Ornamentation: Deep Eaves
 Foundation Material/Form: Concrete/Concrete Block
 Door Detailing:
 Porch: Full Front
 Dormers: Hipped
 Window Type: Double-Hung
 Window Configuration: 1 over 1
 Window Material: Vinyl
 Window Detail:
 Window Storms: No
 Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information: owner

Permit:

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Porch enclosed, October 1953. Joseph Dieter, Owner. 1 room rear addition. March 1957. Joseph Dieter, Owner. Ray F. Carlstedt, Architect.




Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: April 30, 2013



General Information

Street Number: 4720
Former Street Number: 154
Street: MAIN STREET
PIN Number(s): 0908102018

Construction Date/Other Year: 1910s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Poor

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Foursquare

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4721
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908103007

Construction Date/Other Year: 1968

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Good
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Split Level
Number of Stories: 1 ½
Current Wall Material 1: Stone
Current Wall Material 2: Vertical Wood Siding
Original Wall Material 1: Stone
Original Wall Material 2: Vertical Wood Siding
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch:

Dormers:

Window Type: Sliding

Window Configuration:

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4724
Former Street Number: 148
Street: MAIN STREET
PIN Number(s): 0908102019

Construction Date/Other Year: 1910s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: classical porch

Building Form: Foursquare

Number of Stories: 2

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: shutters added



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4725
Former Street Number: 145
Street: MAIN STREET
PIN Number(s): 0908103008

Construction Date/Other Year: 1900s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Gable Front Cottage/House

Number of Stories: 1 ½

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: replacement siding and windows, newer porch, shutters added



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers: Pedimented

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features: original decorative wood window in front, bay window



General Information

Street Number: 4728
 Former Street Number:
 Street: MAIN STREET
 PIN Number(s): 0908102023
 Construction Date/Other Year: 1978
 Architect:
 Current Function/Category: Single Family Residential Building
 Historic Function: Single Family Residential Building
 Listing in Existing Survey:

Evaluation

Condition: Good
 Integrity:
 Secondary Structure: Attached Garage
 Secondary Structure Condition:
 Secondary Structure Integrity:
 Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:
 Ornamentation:
 Building Form:
 Number of Stories: 1 ½
 Current Wall Material 1: Vertical Wood Siding
 Current Wall Material 2:
 Original Wall Material 1:
 Original Wall Material 2:
 Wall Detailing/Ornamentation:
 Storefront Material:
 Roof Type: Front Gabled
 Roof Material: Asphalt Shingle
 Alterations:



Photo 1

Significant: No
 National Register Criterion:
 Contributing to a National Register District: NC
 Potentially Contributing to a National Register District: Noteworthy Buildings
 Less Than 50 Years Old: No
 Reason for Significance:

Roof Ornamentation:
 Foundation Material/Form:
 Door Detailing:
 Porch:
 Dormers:
 Window Type: Casement
 Window Configuration:
 Window Material:
 Window Detail:
 Window Storms:
 Significant Features: stone chimney



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Front (east) Addition. August 1978. Elizabeth Christenson. Owner.
Kafka & Sons. GC. \$35,000.

Horizontal lines for notes




Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: May 29, 2013



General Information

Street Number: 4729
Former Street Number: 145
Street: MAIN STREET
PIN Number(s): 0908103009

Construction Date/Other Year: 1910s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Bungalow

Number of Stories: 1

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: porch infilled, replacement stairs and windows



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail: Paired

Window Storms: Yes

Significant Features:



General Information

Street Number: 4730
Former Street Number: 138
Street: MAIN STREET
PIN Number(s): 0908102024

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation: shingles, decorative porch

Building Form:

Number of Stories: 2

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Wood Shingles

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: replacement windows, shutters added



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance: Excellent example of Queen Anne style.

Roof Ornamentation: Vergeboard

Foundation Material/Form: Stone

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Vinyl

Window Detail:

Window Storms: No

Significant Features: decorative porch, irregular massing



General Information

Street Number: 4733
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908103010

Construction Date/Other Year: 1925

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation: eave brackets, art glass

Building Form: Bungalow

Number of Stories: 1

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: replacement windows



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail: Paired

Window Storms: No

Significant Features: art glass in porch



General Information

Street Number: 4734
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908102021 -27

Construction Date/Other Year: 1925

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Good
Secondary Structure Integrity: Excellent
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Foursquare
Number of Stories: 2
Current Wall Material 1: Brick
Current Wall Material 2:
Original Wall Material 1: Brick
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Full Front

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features:



General Information

Street Number: 4800
 Former Street Number:
 Street: MAIN STREET
 PIN Number(s): 0908109019
 Construction Date/Other Year: 1925
 Architect:
 Current Function/Category: Single Family Residential Building
 Historic Function: Single Family Residential Building
 Listing in Existing Survey:

Evaluation

Condition: Good
 Integrity: Good
 Secondary Structure: Garage
 Secondary Structure Condition: Good
 Secondary Structure Integrity:
 Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:
 Ornamentation:
 Building Form: Bungalow
 Number of Stories: 1 ½
 Current Wall Material 1: Stucco
 Current Wall Material 2:
 Original Wall Material 1: Stucco
 Original Wall Material 2:
 Wall Detailing/Ornamentation:
 Storefront Material:
 Roof Type: Cross gabled
 Roof Material: Asphalt Shingle
 Alterations: a few replacement windows



Photo 1

Significant: No
 National Register Criterion:
 Contributing to a National Register District: C
 Potentially Contributing to a National Register District: Noteworthy Buildings
 Less Than 50 Years Old: No
 Reason for Significance:

Roof Ornamentation:
 Foundation Material/Form: Brick
 Door Detailing:
 Porch: Full Front
 Dormers:
 Window Type: Double-Hung
 Window Configuration: 1 over 1
 Window Material: Wood
 Window Detail:
 Window Storms: Yes
 Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Detached Garage. 1978. Theodore Brown. Owner. Danley Lumber Co. (Stone Park). GC. \$3800.00.

Horizontal lines for note-taking.



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: May 29, 2013



General Information

Street Number: 4804
Former Street Number: 118
Street: MAIN STREET
PIN Number(s): 0908109011

Construction Date/Other Year: 1900s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Gable Front Cottage/House

Number of Stories: 2

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: porch decoration not original, verge board not original



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Vergeboard

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material:

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4810
Former Street Number: 116
Street: MAIN STREET
PIN Number(s): 0908109012

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation: leaded glass transom

Building Form: Gable-Ell

Number of Stories: 2

Current Wall Material 1: Aluminum Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: re-sided, rear addition



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4812
Former Street Number: 114
Street: MAIN STREET
PIN Number(s): 0908109013

Construction Date/Other Year: 1900s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation: decorative porch

Building Form: Gable-Ell

Number of Stories: 1 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Wood Shingles

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: replacement windows, shingles newer



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail: Hood Mold

Window Storms: No

Significant Features: porch



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Horizontal lines for notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: May 29, 2013



General Information

Street Number: 4816

Former Street Number:

Street: MAIN STREET

PIN Number(s): 0908109014

Construction Date/Other Year: 1925

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Chicago Bungalow

Ornamentation:

Building Form: Bungalow

Number of Stories: 1 ½

Current Wall Material 1: Brick

Current Wall Material 2: Fiber Cement

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: 2nd floor addition



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Entrance

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms:

Significant Features: arched entry



General Information

Street Number: 4832
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908109018

Construction Date/Other Year: 1950s

Architect:
Current Function/Category: Institutional Building
Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Attached Garage
Secondary Structure Condition:
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Ornamentation:

Building Form:
Number of Stories: 3
Current Wall Material 1: Brick
Current Wall Material 2: Stone
Original Wall Material 1: Brick
Original Wall Material 2: Stone
Wall Detailing/Ornamentation:

Storefront Material:
Roof Type: Cross gabled
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:
Contributing to a National Register District: C
Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing: Sidelights
Porch: Entrance

Dormers:
Window Type: Casement

Window Configuration:
Window Material: Aluminum

Window Detail:

Window Storms:

Significant Features:



General Information

Street Number: 4900
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908117003

Construction Date/Other Year: 1970

Architect:
Current Function/Category: Commercial Building
Historic Function: Commercial Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity:
Secondary Structure:
Secondary Structure Condition:
Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: International Style

Ornamentation:

Building Form: Strip Commercial
Number of Stories: 1
Current Wall Material 1: Brick
Current Wall Material 2: Vertical Wood Siding
Original Wall Material 1: Brick
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material: Aluminum Framing/Knee Walls
Roof Type: Flat
Roof Material: Not visible/cannot be determined

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Sidelights

Porch:

Dormers:

Window Type: Fixed

Window Configuration:

Window Material: Aluminum

Window Detail:

Window Storms:

Significant Features:



General Information

Street Number: 4905
Former Street Number: 73
Street: MAIN STREET
PIN Number(s): 0908117002

Construction Date/Other Year: 1900s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Commercial Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Poor

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: classical entry surround

Building Form:

Number of Stories: 2

Current Wall Material 1: Aluminum Siding

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: Earlier vernacular house altered and converted to office; porch rebuilt post-WW II.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Full Height

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features:



General Information

Street Number: 4906
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908116016

Construction Date/Other Year: 1980s

Architect:
Current Function/Category: Commercial Building
Historic Function: Commercial Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity:
Secondary Structure:
Secondary Structure Condition:
Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Strip Commercial
Number of Stories: 1
Current Wall Material 1: Brick
Current Wall Material 2:
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Fixed

Window Configuration:

Window Material:

Window Detail:

Window Storms:

Significant Features:



General Information

Street Number: 4912
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908116017

Construction Date/Other Year: 2000s

Architect:
Current Function/Category: Commercial Building
Historic Function:
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity:
Secondary Structure:
Secondary Structure Condition:
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Neo Revival

Ornamentation: cupola

Building Form:
Number of Stories: 2
Current Wall Material 1: Stone
Current Wall Material 2: Fiber Cement
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:
Roof Type: Cross gabled
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No
National Register Criterion:
Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:
Porch: Full Front

Dormers:
Window Type: Double-Hung
Window Configuration: Multi-Paned
Window Material: Vinyl
Window Detail:
Window Storms:

Significant Features: porches



General Information

Street Number: 4913
Former Street Number: 69
Street: MAIN STREET
PIN Number(s): 0908117004

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Commercial Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Gable Front Cottage/House

Number of Stories: 2

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: porch infilled, replacement siding and windows



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Sidelights

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: No

Significant Features:



General Information

Street Number: 4915
Former Street Number: 61
Street: MAIN STREET
PIN Number(s): 0908117005

Construction Date/Other Year: 1910s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Commercial Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation: leaded glass window

Building Form: Foursquare

Number of Stories: 2

Current Wall Material 1: Asbestos Siding

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: porch infilled



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: distinctive asbestos siding



General Information

Street Number: 4919
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908108018

Construction Date/Other Year: 1925

Architect:
Current Function/Category: Commercial Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Good
Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Foursquare
Number of Stories: 2
Current Wall Material 1: Asbestos Siding
Current Wall Material 2:
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: porch enclosed, replacement windows



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms:

Significant Features:



General Information

Street Number: 4920
Former Street Number: 56
Street: MAIN STREET
PIN Number(s): 0908116018-19

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Commercial Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Classical Revival/Beaux Arts

Ornamentation: classical portico

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: porch likely added in 1929, side additions, current brick veneer may date from 1929



Photo 1

Significant: Yes

National Register Criterion: A
C

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance: Long-established funeral home and an excellent example of the Neo-Classical style.

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Transom

Porch: Full Height

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Vinyl

Window Detail: Hood Mold

Window Storms:

Significant Features: portico, by windows



General Information

Street Number: 4923
Former Street Number: 55
Street: MAIN STREET
PIN Number(s): 0908117007

Construction Date/Other Year: 1900s

Architect:

Current Function/Category: Commercial Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Good
Secondary Structure Integrity: Poor
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Foursquare
Number of Stories: 2
Current Wall Material 1: Vinyl Siding
Current Wall Material 2:
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle
Alterations: re-sided, replacement windows, porch enclosed



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung
Window Configuration: 1 over 1
Window Material: Vinyl
Window Detail:
Window Storms:

Significant Features:



General Information

Street Number: 4927
Former Street Number: 51
Street: MAIN STREET
PIN Number(s): 0908117008

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Commercial Building
Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Two-Part Commercial
Number of Stories: 2
Current Wall Material 1: Vinyl Siding
Current Wall Material 2:
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Flat
Roof Material: Not visible/cannot be determined

Alterations: re-sided, storefront enclosed, cornice removed



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch:

Dormers:

Window Type: Double-Hung
Window Configuration: 1 over 1
Window Material: Wood
Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4932
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908116021

Construction Date/Other Year: 1925

Architect:
Current Function/Category: Commercial Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Poor

Secondary Structure:
Secondary Structure Condition:
Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Foursquare
Number of Stories: 2
Current Wall Material 1: Vinyl Siding
Current Wall Material 2: Brick
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material: Wood Framing/Knee Walls
Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: storefront added at front



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch:

Dormers: Hipped
Window Type: Double-Hung
Window Configuration: 1 over 1
Window Material: Vinyl
Window Detail:

Window Storms:

Significant Features:



General Information

Street Number: 4934

Former Street Number:

Street: MAIN STREET

PIN Number(s): 0908116022

Construction Date/Other Year: 1960s

Architect:

Current Function/Category: Commercial Building

Historic Function: Commercial Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Ornamentation:

Building Form: Strip Commercial

Number of Stories: 1

Current Wall Material 1: Stone

Current Wall Material 2: Aluminum Siding

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material: Aluminum Framing/Knee Walls

Roof Type: Flat

Roof Material: Not visible/cannot be determined

Alterations: fascia replaced



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type:

Window Configuration:

Window Material: Aluminum

Window Detail:

Window Storms:

Significant Features:



General Information

Street Number: 4941
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908117009

Construction Date/Other Year: 1925

Architect:
Current Function/Category: Commercial Building
Historic Function: Commercial Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Good

Secondary Structure:
Secondary Structure Condition:
Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Two-Part Commercial
Number of Stories: 2
Current Wall Material 1: Stucco
Current Wall Material 2:
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material: Aluminum Framing/Knee Walls
Roof Type: Flat
Roof Material: Not visible/cannot be determined

Alterations: stucco added, storefront heavily altered



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:
Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms:

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes




Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: May 29, 2013



General Information

Street Number: 4947
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908117032

Construction Date/Other Year: 1925

Architect:
Current Function/Category: Commercial Building
Historic Function: Commercial Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Good

Secondary Structure:
Secondary Structure Condition:
Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Classical Revival/Beaux Arts

Ornamentation: terra cotta ornament

Building Form: One-Part Commercial

Number of Stories: 1

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material: Aluminum Framing/Knee Walls

Roof Type: Front Gabled

Roof Material: Not visible/cannot be determined

Alterations: storefronts altered



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Fixed

Window Configuration:

Window Material: Aluminum

Window Detail:

Window Storms:

Significant Features: terra cotta entry surround



General Information

Street Number: 4954
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908116024

Construction Date/Other Year: 1925

Architect:

Current Function/Category: Commercial Building
Historic Function: Commercial Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Poor

Secondary Structure:
Secondary Structure Condition:
Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Strip Commercial
Number of Stories: 1
Current Wall Material 1: Brick
Current Wall Material 2:
Original Wall Material 1:
Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material: Aluminum Framing/Knee Walls
Roof Type: Mansard
Roof Material: Wood Shingle
Alterations: storefront heavily altered



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC
Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type:

Window Configuration:

Window Material: Aluminum
Window Detail:

Window Storms:

Significant Features:



General Information

Street Number: 4956
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908116025

Construction Date/Other Year: 1950s

Architect:
Current Function/Category: Commercial Building
Historic Function: Commercial Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent

Secondary Structure:
Secondary Structure Condition:
Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Ornamentation:

Building Form: One-Part Commercial
Number of Stories: 1
Current Wall Material 1: Brick
Current Wall Material 2: Stone
Original Wall Material 1: Brick
Original Wall Material 2: Stone
Wall Detailing/Ornamentation:

Storefront Material: Aluminum Framing/Knee Walls
Roof Type: Flat
Roof Material: Not visible/cannot be determined

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:
Porch:

Dormers:
Window Type: Fixed

Window Configuration:
Window Material: Aluminum

Window Detail:

Window Storms:

Significant Features: angled storefronts



General Information

Street Number: 4958
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908116026

Construction Date/Other Year: 1929

Architect:
Current Function/Category: Commercial Building
Historic Function: Commercial Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Good

Secondary Structure:
Secondary Structure Condition:
Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: half timbering

Building Form: Two-Part Commercial

Number of Stories: 2

Current Wall Material 1: Brick
Current Wall Material 2: Stucco
Original Wall Material 1: Brick
Original Wall Material 2: Stucco
Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Front Gabled
Roof Material: Asphalt Shingle

Alterations: storefront infilled with brick, permanent awning



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Vergeboard

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms:

Significant Features: timbering



General Information

Street Number: 5004
Former Street Number:
Street: MAIN STREET
PIN Number(s):

Construction Date/Other Year: 1960s
Architect:
Current Function/Category: Commercial Building
Historic Function: Commercial Building
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure:
Secondary Structure Condition:
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern
Ornamentation:
Building Form: Two-Part Commercial
Number of Stories: 2
Current Wall Material 1: Stone
Current Wall Material 2: Brick
Original Wall Material 1: Stone
Original Wall Material 2: Brick
Wall Detailing/Ornamentation:
Storefront Material: Aluminum Framing/Knee Walls
Roof Type: Flat
Roof Material: Not visible/cannot be determined
Alterations: permanent canopy and shingles added



Photo 1

Significant: No
National Register Criterion:
Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No
Reason for Significance:

Roof Ornamentation:
Foundation Material/Form:
Door Detailing:
Porch:
Dormers:
Window Type: Fixed
Window Configuration:
Window Material: Aluminum
Window Detail:
Window Storms:
Significant Features:



General Information

Street Number: 5002-6
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908116030

Construction Date/Other Year: 1960s

Architect:
Current Function/Category: Commercial Building
Historic Function: Commercial Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Good

Secondary Structure:
Secondary Structure Condition:
Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: One-Part Commercial
Number of Stories: 2
Current Wall Material 1: EIFS
Current Wall Material 2:
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Mansard
Roof Material: Wood Shingle

Alterations: re-sided, new windows and storefront



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Fixed

Window Configuration:

Window Material: Wood

Window Detail:

Window Storms:

Significant Features:



General Information

Street Number: 4928 - 30
Former Street Number: 50
Street: MAIN STREET
PIN Number(s): 0908116020

Construction Date/Other Year: 1900s

Architect:

Current Function/Category: Commercial Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Poor

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Gable Front Cottage/House

Number of Stories: 2

Current Wall Material 1: Vinyl Siding

Current Wall Material 2: Brick

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material: Aluminum Framing/Knee Walls

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: commercial storefront added at front



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms:

Significant Features:



General Information

Street Number: 4946 - 52
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908116023

Construction Date/Other Year: 1990s

Architect:
Current Function/Category: Commercial Building
Historic Function:
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity:
Secondary Structure:
Secondary Structure Condition:
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Strip Commercial
Number of Stories: 1
Current Wall Material 1: Concrete/Concrete Block
Current Wall Material 2: EIFS
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material: Aluminum Framing/Knee Walls
Roof Type: Flat
Roof Material: Not visible/cannot be determined

Alterations:



Photo 1

Significant: No
National Register Criterion:
Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type:

Window Configuration:

Window Material: Aluminum

Window Detail:

Window Storms:

Significant Features:



General Information

Street Number: 5002-5006
Former Street Number:
Street: MAIN STREET
PIN Number(s): 0908116030

Construction Date/Other Year: 1960s

Architect:
Current Function/Category: Commercial Building
Historic Function: Commercial Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good

Secondary Structure:
Secondary Structure Condition:
Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Ornamentation:

Building Form: One-Part Commercial
Number of Stories: 1
Current Wall Material 1: Stone
Current Wall Material 2: Brick
Original Wall Material 1: Stone
Original Wall Material 2: Brick
Wall Detailing/Ornamentation:

Storefront Material: Aluminum Framing/Knee Walls
Roof Type: Flat
Roof Material: Not visible/cannot be determined

Alterations: permanent canopy added



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:
Porch:

Dormers:
Window Type: Fixed

Window Configuration:
Window Material: Aluminum

Window Detail:

Window Storms:

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince's Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes




Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert

Survey Date: May 29, 2013



General Information

Street Number: 4801
 Former Street Number:
 Street: MAIN STREET
 PIN Number(s): 0908110017
 Construction Date/Other Year: 1992
 Architect:
 Current Function/Category: Institutional Building
 Historic Function:
 Listing in Existing Survey:

Evaluation

Condition: Excellent
 Integrity:
 Secondary Structure:
 Secondary Structure Condition:
 Secondary Structure Integrity:
 Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Late Modern Eclectic
 Ornamentation:
 Building Form:
 Number of Stories: 1 ½
 Current Wall Material 1: Brick
 Current Wall Material 2:
 Original Wall Material 1:
 Original Wall Material 2:
 Wall Detailing/Ornamentation:
 Storefront Material:
 Roof Type: Hipped
 Roof Material: Asphalt Shingle
 Alterations:



Photo 1

Significant: No
 National Register Criterion:
 Contributing to a National Register District: NC
 Potentially Contributing to a National Register District: Noteworthy Buildings
 Less Than 50 Years Old: No
 Reason for Significance:

Roof Ornamentation: Cupolas
 Foundation Material/Form: Concrete/Concrete Block
 Door Detailing:
 Porch:
 Dormers: Pedimented
 Window Type: Fixed
 Window Configuration: Art Glass
 Window Material: Aluminum
 Window Detail:
 Window Storms:
 Significant Features:



General Information

Street Number: 4733
Former Street Number:
Street: MIDDAUGH AVENUE
PIN Number(s): 0907205008

Construction Date/Other Year: 1890s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Poor
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Gable-Ell
Number of Stories: 2 ½
Current Wall Material 1: Vinyl Siding
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: This house has been extensively altered, has been re-sided and all windows have been replaced.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail:

Window Storms: No

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information: Dixon Assoc., St. Charles, IL

Contractor Information:

Developer Information: Kubiak Konstruktion, 1990

Research/Archival Information:

Permit: No

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

May 1963 plat of survey shows existing house. Remodel June 1963 for Dr. R.E. Powell, no other info. Second remodel and addition for John Hires in 1990. Dixon & Assoc. architect. Kubiak Konstruktion. GC. 2-car garage added 7/9/1958. Otto Hummer, general contractor & owner. Remodeling 1979 by Normandy Construction; 10/24/79 cert. of occupancy.



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 27, 2013



General Information

Street Number: 4736

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907204022

Construction Date/Other Year: 1977

Architect:

Current Function/Category: Single Family Residential Building

Historic Function:

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity:

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Split Level

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Wood clapboard

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material:

Window Detail: Paired

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

1977. constructed. Mand S Construction. GC. 1978. addition of detached Garage. Hankinson Lumber. GC.

Horizontal lines for notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 20, 2013



General Information

Street Number: 4809
Former Street Number:
Street: MIDDAGH AVENUE
PIN Number(s): 0907212002

Construction Date/Other Year: 2000s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function:
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity:
Secondary Structure: Attached Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Neo Revival

Ornamentation:

Building Form:
Number of Stories: 2 ½
Current Wall Material 1: Brick
Current Wall Material 2: Fiber Cement
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:
Roof Type: Hipped with Cross Gable
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No
National Register Criterion:
Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Sidelights
Porch: Partial
Dormers: Gabled
Window Type: Double-Hung
Window Configuration: Multi-Paned
Window Material: Aluminum
Window Detail:
Window Storms: Yes

Significant Features:



General Information

Street Number: 4816

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907211012

Construction Date/Other Year: 2000s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function:

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity:

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Neo Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Fiber Cement

Current Wall Material 2: EIFS

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Surrounds

Porch: Partial

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Horizontal lines for notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 27, 2013



General Information

Street Number: 4837

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907212009

Construction Date/Other Year: 1950s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Minimal Traditional

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

House was later addition to an earlier one- story house on east elevation.

Horizontal lines for note-taking.



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 25, 2013



General Information

Street Number: 4901
Former Street Number:
Street: MIDDAUGH AVENUE
PIN Number(s): 0907215001

Construction Date/Other Year: 1960s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function:
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity:
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation:
Building Form:
Number of Stories: 2 ½
Current Wall Material 1: Brick
Current Wall Material 2: Vinyl Siding
Original Wall Material 1: Brick
Original Wall Material 2: Wood clapboard
Wall Detailing/Ornamentation:

Storefront Material:
Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No
National Register Criterion:
Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:
Porch: Stoop

Dormers:
Window Type: Double-Hung
Window Configuration: 1 over 1
Window Material: Vinyl
Window Detail:
Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Need to research construction date to see if this is early 1960s and therefore a contributing resource.

Horizontal lines for notes




Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 14, 2013



General Information

Street Number: 4912

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907214014

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Poor

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Foursquare

Number of Stories: 2

Current Wall Material 1: EIFS

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type:

Roof Material: Not visible/cannot be determined

Alterations: Unclear if and when this house, facade and windows had been modified or altered.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Metal

Window Detail:

Window Storms:

Significant Features:



General Information

Street Number: 4916

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907214015

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow

Number of Stories: 1 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: Soffits replaced.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4917

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907215004

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type:

Roof Material: Asphalt Shingle

Alterations: House originally a late Queen Anne that was re-sided in stuccoed at a later date.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: Art Glass

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4920

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907214016

Construction Date/Other Year: 1910s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Foursquare

Number of Stories: 2 ½

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Porch enclosed at later date, some windows replaced on east elevation.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Stone

Door Detailing:

Porch: Full Front

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Masonry porch with capitals



General Information

Street Number: 4921

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907215005

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form:

Number of Stories: 3

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: This house has been re-sided; windows and soffits replaced; new addition on south elevation.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights

Porch: Wrap-Around

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4925

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907215006

Construction Date/Other Year: 1950s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Minimal Traditional

Ornamentation:

Building Form: Ranch

Number of Stories: 1 ½

Current Wall Material 1: Vinyl Siding

Current Wall Material 2: Stone

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Original bay window may have been replaced; re-sided.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4945
Former Street Number:
Street: MIDDAUGH AVENUE
PIN Number(s): 0907215011

Construction Date/Other Year: 1950s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good

Secondary Structure:
Secondary Structure Condition:
Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Minimal Traditional

Ornamentation:

Building Form: Ranch
Number of Stories: 1 ½
Current Wall Material 1: Brick
Current Wall Material 2: Aluminum Siding
Original Wall Material 1: Brick
Original Wall Material 2: Wood clapboard
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 14, 2013



General Information

Street Number: 4704
Former Street Number:
Street: MIDDAUGH AVENUE
PIN Number(s): 0907204014

Construction Date/Other Year: 1890s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Gable-Ell
Number of Stories: 2 ½
Current Wall Material 1: Vinyl Siding
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled
Roof Material: Asphalt Shingle

Alterations: House has later addition on north elevation; house has been re-sided; porch enclosed at later date.



Photo 1

Significant: No
National Register Criterion: B
Contributing to a National Register District: C
Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Sidelights
Porch: Stoop

Dormers:

Window Type: Double-Hung
Window Configuration: Multi-Paned
Window Material: Vinyl
Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Detached garage construction 1978. Hankinson Lumber. GC.



Photo 2



Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 29, 2013



General Information

Street Number: 4708

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907204015

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Gambrel

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: This house retains a high level of integrity.



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Horizontal lines for notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 20, 2013



General Information

Street Number: 4709

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907205002

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation: Bargeboard in gable

Building Form: Gable-Ell

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Porch an front entrance may have been modified, addition on south and rear elevations.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Porch: Entrance

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4712

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907204016

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Gable-Ell

Number of Stories: 2 ½

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: House been re-sided; windows have been replaced on all elevations; porch enclosed.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4713

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907205003

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow

Number of Stories: 1 ½

Current Wall Material 1: Wood Shingles

Current Wall Material 2:

Original Wall Material 1: Wood Shingles

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Soffits replaced, entrance porch modified; windows modified; back porch added.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

1952. addition of detached 2 car garage. 1956. addition of back porch. Architect: Albert H. Namoeede GC: Modern-Aire Homes..

Horizontal lines for note-taking.



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 27, 2013



General Information

Street Number: 4716

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907204017

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Poor

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Vinyl Siding

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Second story full floor addition; windows replaced on all elevations in first floor.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4717
Former Street Number:
Street: MIDDAUGH AVENUE
PIN Number(s): 0907205004

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow
Number of Stories: 1 ½
Current Wall Material 1: Vinyl Siding
Current Wall Material 2:
Original Wall Material 1: Wood Shingles
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: Soffits replaced, addition to the rear.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Sidelights
Porch: Stoop

Dormers:

Window Type: Double-Hung
Window Configuration: Multi-Paned
Window Material: Vinyl
Window Detail: Paired
Window Storms: Yes

Significant Features:



General Information

Street Number: 4720

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907204018

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Foursquare

Number of Stories: 3

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: House has been re-sided; south entrance remodeled in a Colonial Revival motif.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms:

Significant Features:



General Information

Street Number: 4721

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907205005

Construction Date/Other Year: 1950

Architect: Jane Jacobsen

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Poor

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Minimal Traditional

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: New porch - not original to the house; new addition being added to east elevation at time of survey.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material:

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

1950. residence erected. Jane Jacobsen. Architect: 1952 addition of detached garage.

Horizontal lines for note-taking.



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 27, 2013



General Information

Street Number: 4724

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907204019

Construction Date/Other Year: 1950s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Ornamentation:

Building Form: Ranch

Number of Stories: 1 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Stoop

Dormers:

Window Type: Casement

Window Configuration:

Window Material: Metal

Window Detail:

Window Storms: No

Significant Features:



General Information

Street Number: 4725

Former Street Number:

Street: MIDDAGH AVENUE

PIN Number(s): 0907206013

Construction Date/Other Year: 1969

Architect:

Current Function/Category: Single Family Residential Building

Historic Function:

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity:

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Late Modern Eclectic

Ornamentation:

Building Form: Split Level

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Wood clapboard

Original Wall Material 1: Brick

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Stoop

Dormers:

Window Type: Casement

Window Configuration:

Window Material: Metal

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4728

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907204020

Construction Date/Other Year: 1950s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function:

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity:

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: EIFS

Current Wall Material 2: Brick

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: This house appears to be significantly altered.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration:

Window Material: Metal

Window Detail:

Window Storms: No

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

1954. addition of detached 2 car garage. Carl Newman. GC. 1986.
Addition of deck.

Horizontal lines for note-taking.



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 20, 2013



General Information

Street Number: 4729

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907205007

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Poor

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Gable Front Cottage/House

Number of Stories: 2 ½

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: House has been re-sided with new windows on all elevation, original porch has been moved at some



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Terrace

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

1977. foundation repair. 1978. remodeled walls and chimney. 1985. addition of garage.

Horizontal lines for handwritten notes.



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 27, 2013



General Information

Street Number: 4732

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907204021

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Porch enclosed at later date; garage may be of recent construction.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4737

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907205009

Construction Date/Other Year: 1950s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Wood clapboard

Original Wall Material 1: Brick

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations: Unclear what house's original style was given second story addition.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Sidelights

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail: Paired

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

1964. addition of detached garage. 1983. addition of second story.
1998. remodel of second story. John Kraug. GC.

Horizontal lines for additional notes.



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 27, 2013



General Information

Street Number: 4741

Former Street Number:

Street: MIDDLEDAUGH AVENUE

PIN Number(s): 0907205010

Construction Date/Other Year: 2000s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function:

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity:

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Neo Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: EIFS

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Sidelights

Porch: Entrance

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes




Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 27, 2013



General Information

Street Number: 4743

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907205011

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: Addition on east elevation, house was re- sided



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Surrounds

Porch: Entrance

Dormers: Shed

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Horizontal lines for notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 27, 2013



General Information

Street Number: 4744
Former Street Number:
Street: MIDDAUGH AVENUE
PIN Number(s): 0907204023-24

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow
Number of Stories: 2
Current Wall Material 1: Stucco
Current Wall Material 2: Wood Shingles
Original Wall Material 1: Stucco
Original Wall Material 2: Wood Shingles
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance: Outstanding example of a Craftsman Bungalow home with Colonial Revival ornamentation and detailing. It retains a high level of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Wrap-Around

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Wrap-around porch with columns; gable over porch; Craftsman dormer on north elevation.



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 29, 2013



General Information

Street Number: 4800
Former Street Number:
Street: MIDDAUGH AVENUE
PIN Number(s): 0907211010

Construction Date/Other Year: 1910s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow
Number of Stories: 1 ½
Current Wall Material 1: Brick
Current Wall Material 2: Stone
Original Wall Material 1: Brick
Original Wall Material 2: Stone
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable
Roof Material: Tile

Alterations: Some windows have been replaced on east elevation with casements; soffits replaced.



Photo 1

Significant: Yes
National Register Criterion: C
Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance: A distinctive example of a Craftsman Bungalow with tile roof and a high level of integrity.

Roof Ornamentation: Deep Eaves
Foundation Material/Form: Not visible/cannot be determined

Door Detailing:
Porch: Entrance
Dormers: Hipped
Window Type: Double-Hung
Window Configuration: 1 over 1
Window Material: Wood
Window Detail:
Window Storms: Yes

Significant Features: Side porch, tile roof.



General Information

Street Number: 4808
Former Street Number:
Street: MIDDLEDAUGH AVENUE
PIN Number(s): 0907211011

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow
Number of Stories: 2
Current Wall Material 1: Wood clapboard
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled
Roof Material: Asphalt Shingle

Alterations: Knee brackets may be missing under eaves.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Entrance

Dormers: Shed

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 29, 2013



General Information

Street Number: 4813

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907212003

Construction Date/Other Year: 2000s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function:

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity:

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Neo Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Fiber Cement

Current Wall Material 2: Stone

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Sidelights

Porch: Partial

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail: Paired

Window Storms: Yes

Significant Features:



General Information

Street Number: 4817

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907212004

Construction Date/Other Year: 2000s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function:

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity:

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Neo Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Stone

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Transom

Porch: Partial

Dormers: Pedimented

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 17, 2013



General Information

Street Number: 4820
Former Street Number:
Street: MIDDAUGH AVENUE
PIN Number(s): 0907211013

Construction Date/Other Year: 1950
Architect: A. H. Nemoede
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Minimal Traditional

Ornamentation:

Building Form:
Number of Stories: 2 ½
Current Wall Material 1: Wood Shingles
Current Wall Material 2:
Original Wall Material 1: Wood Shingles
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled
Roof Material: Asphalt Shingle

Alterations: Some modification/alteration above doorway on east elevation.



Photo 1

Significant: No
National Register Criterion:
Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Surrounds
Porch: Entrance

Dormers:
Window Type: Double-Hung
Window Configuration: Multi-Paned
Window Material: Vinyl
Window Detail:
Window Storms: Yes

Significant Features:



General Information

Street Number: 4821
Former Street Number:
Street: MIDDAUGH AVENUE
PIN Number(s): 0907212005

Construction Date/Other Year: 1950s
Architect: R.F. Carlstedt
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Poor
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:
Ornamentation:
Building Form:
Number of Stories: 2 ½
Current Wall Material 1: Vinyl Siding
Current Wall Material 2: Brick
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:
Storefront Material:
Roof Type: Hipped with Cross Gable
Roof Material: Asphalt Shingle
Alterations: Unclear of the original architectural style given second story addition and new porch.



Photo 1

Significant: No
National Register Criterion:
Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No
Reason for Significance:

Roof Ornamentation:
Foundation Material/Form: Not visible/cannot be determined
Door Detailing:
Porch: Full Front
Dormers:
Window Type: Double-Hung
Window Configuration: Multi-Paned
Window Material: Aluminum
Window Detail:
Window Storms: Yes
Significant Features:



General Information

Street Number: 4825

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907212006

Construction Date/Other Year: 1960s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Aluminum Siding

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations: Addition on east elevation.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Terrace

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Need to research construction date to see if this is early 1960s and therefore a contributing resource. This may be a later house.

Horizontal lines for note-taking.



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 27, 2013



General Information

Street Number: 4828

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907211014

Construction Date/Other Year: 1910s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Foursquare

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance: A distinctive Prairie Foursquare in masonry rather than wood construction. It also retains a high level of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Sidelights

Porch: Entrance

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: Brick Foursquare.



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 14, 2013



General Information

Street Number: 4829

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907212007

Construction Date/Other Year: 2000s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function:

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity:

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Neo Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Fiber Cement

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Sidelights

Porch: Stoop

Dormers: Gabled

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail:

Window Storms: No

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 27, 2013



General Information

Street Number: 4833

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907212008

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Vinyl Siding

Current Wall Material 2: Wood Shingles

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: This house has been re- sided; dormers could be new additions; house may have front addition.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Full Front

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Horizontal lines for notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 27, 2013



General Information

Street Number: 4836

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907211015

Construction Date/Other Year: 1880s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Wood Shingles

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: Porch enclosed and remodeled. Addition may have been added to west elevation at later date.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Porch: Wrap-Around

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: Porch on east elevation.



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Horizontal lines for notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 14, 2013



General Information

Street Number: 4900
Former Street Number:
Street: MIDDAUGH AVENUE
PIN Number(s): 0907214011

Construction Date/Other Year: 1970s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function:
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity:
Secondary Structure: Attached Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Split Level
Number of Stories: 2 ½
Current Wall Material 1: Brick
Current Wall Material 2: Wood clapboard
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No
National Register Criterion:
Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:
Porch: Stoop

Dormers:
Window Type: Sliding
Window Configuration: 1 over 1
Window Material: Metal
Window Detail:
Window Storms: Yes

Significant Features:



General Information

Street Number: 4904

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907214012

Construction Date/Other Year: 1910s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Foursquare

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2: Wood clapboard

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Porch enclosed at some point, soffits and front entrance door replaced.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Stoop

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4908
Former Street Number:
Street: MIDDAUGH AVENUE
PIN Number(s): 0907214013

Construction Date/Other Year: 1900s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Foursquare
Number of Stories: 2 ½
Current Wall Material 1: Stucco
Current Wall Material 2:
Original Wall Material 1: Stucco
Original Wall Material 2:
Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: Some windows have been replaced on east elevation, soffits replaced.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds
Porch: Stoop

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail:

Window Storms: Yes

Significant Features: Enclosed porch.



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 14, 2013



General Information

Street Number: 4909

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907215002

Construction Date/Other Year: 1930s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations: Garage appears to be new construction; pergola added on north elevation.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Brick

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4913

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907215003

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow

Number of Stories: 1 ½

Current Wall Material 1: Wood Shingles

Current Wall Material 2: Vinyl Siding

Original Wall Material 1: Wood Shingles

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Soffits replaced along with some wood clapboarding in porch roof. New storm windows installed.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features:



General Information

Street Number: 4924

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907214017

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Vinyl Siding

Original Wall Material 1: Brick

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations: Vinyl siding in dormer, side gables and first east bay. Garage is new construction.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Entrance

Dormers: Shed

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail: Paired

Window Storms: Yes

Significant Features:



General Information

Street Number: 4928

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907214018

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow

Number of Stories: 2

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Front entrance bay has been modified with bay window and door entrance



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Sidelights

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4929

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907215007

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Gable Front Cottage/House

Number of Stories: 3

Current Wall Material 1: Vinyl Siding

Current Wall Material 2: Wood Shingles

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: Addition constructed to east elevation, re-sided with vinyl; some windows replaced; porch



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Entrance

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4932

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907214019

Construction Date/Other Year: 1940s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Minimal Traditional

Ornamentation:

Building Form: Ranch

Number of Stories: 1 ½

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4933
Former Street Number:
Street: MIDDAUGH AVENUE
PIN Number(s): 0907215008

Construction Date/Other Year: 1910s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow
Number of Stories: 1 ½
Current Wall Material 1: Wood clapboard
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material:

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 14, 2013



General Information

Street Number: 4937

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907215009

Construction Date/Other Year: 1950s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Poor

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Minimal Traditional

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Aluminum Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: Addition to the east elevation, original bay window may have been replaced.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: No

Significant Features:



General Information

Street Number: 4941
Former Street Number:
Street: MIDDAUGH AVENUE
PIN Number(s): 0907215010

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Poor
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form:
Number of Stories: 2 ½
Current Wall Material 1: Vinyl Siding
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled
Roof Material: Asphalt Shingle

Alterations: House has been re-sided with changes to the west elevation dormer.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:
Porch: Stoop
Dormers: Gabled
Window Type: Casement
Window Configuration: Multi-Paned
Window Material: Wood
Window Detail:
Window Storms: Yes

Significant Features:



General Information

Street Number: 4944

Former Street Number:

Street: MIDDAUGH AVENUE

PIN Number(s): 0907214021-22

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Poor

Integrity: Good

Secondary Structure: Carriage House

Secondary Structure Condition: Good

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Gable Front Cottage/House

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Wood Shingles

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: Addition to the west, house may have been remodeled and refaced at some point in the past.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4700

Former Street Number:

Street: OAKWOOD AVENUE

PIN Number(s): 0907203002

Construction Date/Other Year: 2000s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function:

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity:

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Neo Revival

Ornamentation:

Building Form: Ranch

Number of Stories: 2

Current Wall Material 1: Fiber Cement

Current Wall Material 2: Stone

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers: Hipped

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Horizontal lines for notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 20, 2013



General Information

Street Number: 4709

Former Street Number:

Street: OAKWOOD AVENUE

PIN Number(s): 0907204003-05

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Wing on south elevation may have been a later addition.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Stone

Door Detailing: Sidelights

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4727
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907204008
Construction Date/Other Year: 1960s
Architect:
Current Function/Category: Single Family Residential Building
Historic Function:
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity:
Secondary Structure: Attached Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:
Ornamentation:
Building Form: Split Level
Number of Stories: 1 ½
Current Wall Material 1: Brick
Current Wall Material 2: Wood clapboard
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:
Storefront Material:
Roof Type: Hipped
Roof Material: Asphalt Shingle
Alterations:



Photo 1

Significant: No
National Register Criterion:
Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No
Reason for Significance:
Roof Ornamentation: Deep Eaves
Foundation Material/Form: Not visible/cannot be determined
Door Detailing: Sidelights
Porch: Terrace
Dormers:
Window Type: Double-Hung
Window Configuration: 1 over 1
Window Material:
Window Detail: Paired
Window Storms: Yes
Significant Features:



General Information

Street Number: 4728

Former Street Number:

Street: OAKWOOD AVENUE

PIN Number(s): 0907203009

Construction Date/Other Year: 1950s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Minimal Traditional

Ornamentation:

Building Form:

Number of Stories: 1 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Metal

Window Detail:

Window Storms: Yes

Significant Features: Wood paneling in gables, stone chimney; front bay window.



General Information

Street Number: 4735
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907204011

Construction Date/Other Year: 2000s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function:
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity:
Secondary Structure: Attached Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Neo Revival

Ornamentation:
Building Form:
Number of Stories: 2 ½
Current Wall Material 1: Brick
Current Wall Material 2: Vinyl Siding
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:
Roof Type: Hipped with Cross Gable
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No
National Register Criterion:
Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights
Porch: Entrance

Dormers:
Window Type: Double-Hung
Window Configuration: Multi-Paned
Window Material: Aluminum
Window Detail: Paired
Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: April 30, 2013



General Information

Street Number: 4801
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907211001

Construction Date/Other Year: 1970s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function:

Listing in Existing Survey:




Photo 1

Evaluation

Condition: Excellent
Integrity:
Secondary Structure: Attached Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Significant: No
National Register Criterion:
Contributing to a National Register District: NC
Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Architectural Descriptions

Architectural Classification/Style: Late Modern Eclectic

Ornamentation:

Building Form: Split Level
Number of Stories: 1 ½
Current Wall Material 1: Brick
Current Wall Material 2: Vertical Wood Siding
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:
Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:
Porch: Stoop

Dormers:
Window Type: Casement

Window Configuration:
Window Material:
Window Detail:

Window Storms:

Significant Features:



General Information

Street Number: 4809
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907211003

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½
Current Wall Material 1: Brick
Current Wall Material 2: Stone
Original Wall Material 1: Brick
Original Wall Material 2: Stone
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No
National Register Criterion: C
Contributing to a National Register District: C
Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch: Stoop

Dormers: Gabled

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4821
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907211016-17

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Foursquare
Number of Stories: 2 ½
Current Wall Material 1: Vinyl Siding
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: Porch was enclosed at later date; garage may have had an addition on south elevation.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Sidelights
Porch: Full Front

Dormers:

Window Type: Double-Hung
Window Configuration: 1 over 1
Window Material: Vinyl
Window Detail: Paired
Window Storms: Yes

Significant Features:



General Information

Street Number: 4825
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907211006

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Foursquare
Number of Stories: 2 ½
Current Wall Material 1: Vinyl Siding
Current Wall Material 2: Brick
Original Wall Material 1: Wood clapboard
Original Wall Material 2: Brick
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: House has been re-sided and original porch and west one story wing may have been altered



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4828
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907210031-32

Construction Date/Other Year: 1890s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Excellent
Secondary Structure: Carriage House
Secondary Structure Condition: Good
Secondary Structure Integrity: Excellent
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation: Shingling pattern on upper two stories.
Building Form:
Number of Stories: 2 ½
Current Wall Material 1: Wood clapboard
Current Wall Material 2: Wood Shingles
Original Wall Material 1: Wood clapboard
Original Wall Material 2: Wood Shingles
Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:
Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: Porch elements such as columns and railings have been replaced. Rear addition added at a later date.



Photo 1

Significant: Yes
National Register Criterion: C
Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance: Intact carriage/coach house; highly intact Queen Anne home.

Roof Ornamentation:
Foundation Material/Form: Stone
Door Detailing: Surrounds
Porch: Full Front
Dormers:
Window Type: Double-Hung
Window Configuration: 1 over 1
Window Material: Wood
Window Detail:
Window Storms: Yes

Significant Features: Top blind gable; coach house in rear.



General Information

Street Number: 4829
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907211008

Construction Date/Other Year: 1890s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Gable-Ell
Number of Stories: 2 ½
Current Wall Material 1: Wood clapboard
Current Wall Material 2: Wood Shingles
Original Wall Material 1: Wood clapboard
Original Wall Material 2: Wood Shingles
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance: House is scheduled to be demolished.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features:



General Information

Street Number: 4833
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907211008

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Bungalow
Number of Stories: 1 ½
Current Wall Material 1: Wood clapboard
Current Wall Material 2:
Original Wall Material 1: Stucco
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights
Porch: Stoop

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: April 30, 2013



General Information

Street Number: 4840
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907210035

Construction Date/Other Year: 1910s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Foursquare
Number of Stories: 2 ½
Current Wall Material 1: Wood clapboard
Current Wall Material 2: Stucco
Original Wall Material 1: Wood clapboard
Original Wall Material 2: Stucco
Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: Windows on second floor have been replaced.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Stone

Door Detailing: Surrounds
Porch: Full Front

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail:

Window Storms: Yes

Significant Features: Craftsman/Prairie styled porch.



General Information

Street Number: 4901
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907214028

Construction Date/Other Year: 1890s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Foursquare
Number of Stories: 2 ½
Current Wall Material 1: Wood clapboard
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds
Porch: Full Front

Dormers:

Window Type: Double-Hung
Window Configuration: 1 over 1
Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4905
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907214029

Construction Date/Other Year: 2000s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function:
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity:
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Neo Revival

Ornamentation:
Building Form:
Number of Stories: 2 ½
Current Wall Material 1: Fiber Cement
Current Wall Material 2:
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:
Roof Type: Hipped with Cross Gable
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No
National Register Criterion:
Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:
Porch: Partial

Dormers:
Window Type: Double-Hung
Window Configuration: Multi-Paned
Window Material: Aluminum
Window Detail:
Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 14, 2013



General Information

Street Number: 4920
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907210041

Construction Date/Other Year: 2000s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function:
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity:
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Neo Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½
Current Wall Material 1: Fiber Cement
Current Wall Material 2: Stone
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:
Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No
National Register Criterion:
Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Transom
Porch: Full Front
Dormers: Arched
Window Type: Casement
Window Configuration: Multi-Paned
Window Material: Aluminum
Window Detail:
Window Storms: No

Significant Features:



General Information

Street Number: 4924

Former Street Number:

Street: OAKWOOD AVENUE

PIN Number(s): 0907210049

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Gable-Ell

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Original porch area had been enclosed or modified at some point in the past.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Sidelights

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Investigation needed to determine when porch enclosure took place.

Horizontal lines for note-taking.



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: April 30, 2013



General Information

Street Number: 4933
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907214007

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Good
Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow
Number of Stories: 1 ½
Current Wall Material 1: Aluminum Siding
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable
Roof Material: Asphalt Shingle

Alterations: House has been re-sided and soffits replaced.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: Art Glass

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home: Yes

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 14, 2013



General Information

Street Number: 4703

Former Street Number:

Street: OAKWOOD AVENUE

PIN Number(s): 0907204001-02

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Gambrel

Roof Material: Asphalt Shingle

Alterations: Second story addition on east elevation; soffits have been replaced.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4714

Former Street Number:

Street: OAKWOOD AVENUE

PIN Number(s): 0907204005

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form:

Number of Stories: 3

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Wood clapboard

Original Wall Material 1: Wood Shingles

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: Gazebo added to south elevation; some window replacements.



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a National Register District: B

Potentially Contributing to a National Register District: C

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance: A highly distinctive Queen Anne home with excellent architectural integrity; home to E.H. Prince.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Porch: Wrap-Around

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material:

Window Detail:

Window Storms: Yes

Significant Features: Over massing; gable dormers, band boarding around some windows.



General Information

Street Number: 4715

Former Street Number:

Street: OAKWOOD AVENUE

PIN Number(s): 0907204006-07

Construction Date/Other Year: 1910s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation:

Building Form: Foursquare

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance: A highly distinctive Prairie Foursquare with some Colonial Revival elements that has retained a high level of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Stone

Door Detailing: Sidelights

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Intact porch; clapboard siding; wide roof eaves.



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: April 30, 2013



General Information

Street Number: 4732

Former Street Number:

Street: OAKWOOD AVENUE

PIN Number(s): 0907203010-11

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Good

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Gable-Ell

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Wood Shingles

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Some windows on east elevation have been replaced; front steps have been replaced.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material:

Window Detail:

Window Storms: Yes

Significant Features: Bowed gable with shingle pattern; large yard.



General Information

Street Number: 4740

Former Street Number:

Street: OAKWOOD AVENUE

PIN Number(s): 0907203015

Construction Date/Other Year: 1900s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: House was originally a Queen Anne but a later Craftsman porch was added.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4741
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907204012-13

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building
Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation:

Building Form:
Number of Stories: 2 ½
Current Wall Material 1: Stucco
Current Wall Material 2: Vinyl Siding
Original Wall Material 1: Stucco
Original Wall Material 2: Wood clapboard
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Gambrel
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No
National Register Criterion:
Contributing to a National Register District: C
Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds
Porch: Full Front

Dormers:
Window Type: Double-Hung
Window Configuration: 1 over 1
Window Material: Wood
Window Detail:
Window Storms: Yes

Significant Features:



General Information

Street Number: 4800
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907210024

Construction Date/Other Year: 1910s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building
Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:
Number of Stories: 2 ½
Current Wall Material 1: Stucco
Current Wall Material 2:
Original Wall Material 1: Stucco
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled
Roof Material: Asphalt Shingle

Alterations: Front trellis added at later date; one story additions on west elevation.



Photo 1

Significant: No
National Register Criterion:
Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance: A highly distinctive Prairie Foursquare that has retained a high level of integrity.

Roof Ornamentation: Deep Eaves
Foundation Material/Form: Not visible/cannot be determined

Door Detailing:
Porch: Terrace
Dormers:
Window Type: Double-Hung
Window Configuration: Multi-Paned
Window Material: Wood
Window Detail:
Window Storms: Yes

Significant Features:



General Information

Street Number: 4804
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907210025

Construction Date/Other Year: 1960s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function:
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity:
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Minimal Traditional

Ornamentation:

Building Form: Split Level
Number of Stories: 1 ½
Current Wall Material 1: Wood clapboard
Current Wall Material 2: Vertical Wood Siding
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Partial

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4805
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907211002

Construction Date/Other Year: 1910s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good

Secondary Structure:
Secondary Structure Condition:
Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Fiber Cement
Current Wall Material 2:

Original Wall Material 1: Wood clapboard
Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable
Roof Material: Asphalt Shingle

Alterations: This house has had several modifications to the porch and additions on east elevations.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Wrap-Around

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4808

Former Street Number:

Street: OAKWOOD AVENUE

PIN Number(s): 0907210026

Construction Date/Other Year: 1910s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Foursquare

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2: Vinyl Siding

Original Wall Material 1: Stucco

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Some windows may have been replaced.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch: Full Front

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4812
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907210027-28

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow
Number of Stories: 1 ½
Current Wall Material 1: Brick
Current Wall Material 2: Wood Shingles
Original Wall Material 1: Brick
Original Wall Material 2: Wood Shingles
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: Soffits have been replaced.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Art Glass

Window Material: Wood

Window Detail: Ribbon

Window Storms: Yes

Significant Features:



General Information

Street Number: 4813
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907211004

Construction Date/Other Year: 1890s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form: Foursquare
Number of Stories: 2 ½
Current Wall Material 1: Wood clapboard
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: Porch was enclosed at some point in the past.



Photo 1

Significant: No

National Register Criterion: C

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Sidelights
Porch: Full Front

Dormers:

Window Type: Double-Hung
Window Configuration: 1 over 1
Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Queen Anne bay and gable on south elevation.



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Interesting Gable-ELL building form to what may have been an older Italianate farmhouse.

Horizontal lines for note-taking.



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: April 30, 2013



General Information

Street Number: 4820

Former Street Number:

Street: OAKWOOD AVENUE

PIN Number(s): 0907210029-30

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2: Vinyl Siding

Original Wall Material 1: Stone

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Vinyl/substitute siding on tower and gable.



Photo 1

Significant: No

National Register Criterion: C

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance: Although this house has lost some integrity, it remains a unique example of a towered/turreted Queen with distinctive use of stone as a primary building material.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Stone

Door Detailing:

Porch: Partial

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Hood Mold

Window Storms: Yes

Significant Features: Tower on south/east elevation.



General Information

Street Number: 4832
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907210033

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow
Number of Stories: 2
Current Wall Material 1: Brick
Current Wall Material 2: Wood Shingles
Original Wall Material 1: Brick
Original Wall Material 2: Wood Shingles
Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Shingling in gables is a unique feature of house.



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: April 30, 2013



General Information

Street Number: 4837
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907211009

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow
Number of Stories: 1 ½
Current Wall Material 1: Wood clapboard
Current Wall Material 2:
Original Wall Material 1: Stucco
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: Some windows have been removed.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4904
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907210037

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form:
Number of Stories: 2 ½
Current Wall Material 1: Stucco
Current Wall Material 2:
Original Wall Material 1: Stucco
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: Front door replaced.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Transom
Porch: Stoop
Dormers: Hipped
Window Type: Double-Hung
Window Configuration: 1 over 1
Window Material: Wood
Window Detail:
Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Need to investigate when asbestos siding was installed to the house. House may have some original siding left underneath current. This house could be NR eligible if artificial siding is removed and original siding investigated.



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: April 30, 2013



General Information

Street Number: 4909
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907210038

Construction Date/Other Year: 2000s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function:
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity:
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Neo Revival

Ornamentation:
Building Form:
Number of Stories: 3
Current Wall Material 1: Fiber Cement
Current Wall Material 2:
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:
Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No
National Register Criterion:
Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Sidelights
Porch: Full Front

Dormers:
Window Type: Double-Hung
Window Configuration: Multi-Paned
Window Material: Aluminum
Window Detail:
Window Storms: Yes

Significant Features:



General Information

Street Number: 4912
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907210039

Construction Date/Other Year: 1980s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function:
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity:
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Neo Revival

Ornamentation:

Building Form: Split Level
Number of Stories: 2 ½
Current Wall Material 1: Brick
Current Wall Material 2: Vinyl Siding
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4913

Former Street Number:

Street: OAKWOOD AVENUE

PIN Number(s): 0907214003

Construction Date/Other Year: 1880s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Gable-Ell

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Porch may have been altered at later date; bay window on west elevation is a later alteration.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Brick

Door Detailing:

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features: Distinctive window trim and crown moldings



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Horizontal lines for notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 14, 2013



General Information

Street Number: 4916
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907210040

Construction Date/Other Year: 1900s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form:
Number of Stories: 2 ½
Current Wall Material 1: Wood clapboard
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable
Roof Material: Wood Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Porch: Partial

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features: Windows have been replaced on all elevations. Porch originally may have been on front entrance.



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Additional research needed to determine earlier changes to house.
Redwood siding may be later addition to house.



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: April 30, 2013



General Information

Street Number: 4928
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907210044-50

Construction Date/Other Year: 1890s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building
Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Good
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Good
Secondary Structure Integrity: Excellent
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Gable-El
Number of Stories: 2 ½
Current Wall Material 1: Wood clapboard
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled
Roof Material: Asphalt Shingle

Alterations: Porch may have been modified at a later date with enclosed knee wall.



Photo 1

Significant: Yes
National Register Criterion: C
Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance: Excellent example of a vernacular Gable-El house that has retained a high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds
Porch: Full Front

Dormers:

Window Type: Double-Hung
Window Configuration: 1 over 1
Window Material: Wood
Window Detail:
Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: April 30, 2013



General Information

Street Number: 4929
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907214006

Construction Date/Other Year: 1896

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Good
Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Gable Front Cottage/House
Number of Stories: 2 ½
Current Wall Material 1: Wood clapboard
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds
Porch: Full Front

Dormers:

Window Type: Double-Hung
Window Configuration: 1 over 1
Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 14, 2013



General Information

Street Number: 4936
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907210045

Construction Date/Other Year: 1890s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building
Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent
Integrity: Excellent
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Gable-El
Number of Stories: 2 ½
Current Wall Material 1: Wood clapboard
Current Wall Material 2: Wood Shingles
Original Wall Material 1: Wood clapboard
Original Wall Material 2: Wood Shingles
Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Front Gabled
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: Yes
National Register Criterion: C
Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance: Excellent example of a vernacular Gable-El House in excellent conditions and a high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Transom
Porch: Full Front

Dormers:

Window Type: Double-Hung
Window Configuration: 1 over 1
Window Material: Wood
Window Detail: Paired
Window Storms: Yes

Significant Features: Shingle pattern in top east gable, which may not be original to house-needs investigation.



General Information

Street Number: 4937

Former Street Number:

Street: OAKWOOD AVENUE

PIN Number(s): 0907214008

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Poor

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Gable Front Cottage/House

Number of Stories: 2 ½

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: Significant alterations including residing, window replacements, porch modifications.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Sidelights

Porch: Stoop

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Metal

Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4940
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907210046

Construction Date/Other Year: 1900s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation: Wood shingling in top east gable.

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Vinyl Siding

Current Wall Material 2: Wood Shingles

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Addition on west elevation; original wood siding was removed according to property owner.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: April 30, 2012



General Information

Street Number: 4941
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907214009

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure: Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity: Good
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow
Number of Stories: 2
Current Wall Material 1: Stucco
Current Wall Material 2:
Original Wall Material 1: Stucco
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: Soffits and windows replaced on all elevations; some knee brackets may be missing; front door has



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Sidelights
Porch: Stoop

Dormers:

Window Type: Double-Hung
Window Configuration: Multi-Paned
Window Material: Vinyl
Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 27, 2013



General Information

Street Number: 4944

Former Street Number:

Street: OAKWOOD AVENUE

PIN Number(s): 0907210047

Construction Date/Other Year: 1970s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function:

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity:

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Late Modern Eclectic

Ornamentation:

Building Form: Split Level

Number of Stories: 2

Current Wall Material 1: Vertical Wood Siding

Current Wall Material 2: Brick

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Sidelights

Porch: Terrace

Dormers:

Window Type: Casement

Window Configuration: Other

Window Material: Aluminum

Window Detail:

Window Storms: No

Significant Features:



General Information

Street Number: 4945
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907214023

Construction Date/Other Year: 1920s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Excellent

Secondary Structure:
Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow
Number of Stories: 1 ½
Current Wall Material 1: Stucco
Current Wall Material 2:
Original Wall Material 1: Stucco
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations: Soffits have been replaced; some knee brackets may be missing.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Stoop

Dormers:

Window Type: Double-Hung
Window Configuration: 1 over 1
Window Material: Vinyl
Window Detail:

Window Storms: Yes

Significant Features:



General Information

Street Number: 4949
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907214024

Construction Date/Other Year: 1890s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity: Good
Secondary Structure: Attached Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Gable-Ell
Number of Stories: 2 ½
Current Wall Material 1: Vinyl Siding
Current Wall Material 2:
Original Wall Material 1: Wood clapboard
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled
Roof Material: Asphalt Shingle

Alterations: Addition with attached garage on north elevation; most windows replaced on all elevations.



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: C
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation:

Foundation Material/Form: Stucco

Door Detailing: Transom

Porch: Stoop

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision: E.H. Prince Subdivision

Landscape/Streetscape:

Sears Catalog Home:

Notes

Horizontal lines for notes



Photo 2




Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis

Survey Date: June 27, 2013



General Information

Street Number: 4950
Former Street Number:
Street: OAKWOOD AVENUE
PIN Number(s): 0907210048

Construction Date/Other Year: 1970s

Architect:
Current Function/Category: Single Family Residential Building
Historic Function:
Listing in Existing Survey:

Evaluation

Condition: Excellent
Integrity:
Secondary Structure: Attached Garage
Secondary Structure Condition: Excellent
Secondary Structure Integrity:
Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Late Modern Eclectic

Ornamentation:

Building Form: Split Level
Number of Stories: 2
Current Wall Material 1: Brick
Current Wall Material 2: Vertical Wood Siding
Original Wall Material 1:
Original Wall Material 2:
Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped
Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: No

National Register Criterion:

Contributing to a National Register District: NC
Potentially Contributing to a National Register District:
Noteworthy Buildings Less Than 50 Years Old: No

Reason for Significance:

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Sidelights
Porch: Terrace

Dormers:

Window Type: Casement

Window Configuration: Other

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:

